# Bode Middle School




## BUILDING SCORE

building score can range from 1.00 - 4.00

ALL BUILDING SCORE AVERAGE **2.51** 

	Bode Middle School	Buildings of Similar Age	All District Buildings
<b>ENVIRONMENT</b> Five factors ranked on a scale of 1-4	2.30	2.55	2.70
<b>PHYSICAL CONDITION</b> Condition of the building, site, and furnishings, ranked on a scale of 1-4	2.31	2.27	2.44
<b>SYSTEMS</b> Conditions of mechanical, electrical, and plumbing systems ranked on a scale of 1-4	2.03	2.24	2.43
OVERALL SCORE Average of all date points gathered	2.20	2.36	2.51



DLR Group

### **Bode Middle School**

#### CAPACITY

DESE Max. Capacity	Optimum Capacity	18-19 Enrollment	5 YR Projection	10 YR Projection
510	460	501	503	484

#### CONSTRUCTION

66,606 SF

1926 Original	57,832 SF
1966 Addition	14,480 SF
2002 Addition	11,800 SF

#### SQUARE FEET PER STUDENT

Low for this building type **High** for this building type

114 SF / 133 SF / 133 SF

#### STRENGTH + CHALLENGES

#### STRENGTHS

- Exterior appeal and community presence
- Integrity and strength of the structure
- · Exterior windows are newer and reasonably energy efficient
- Flat roof conditions
- Solar array
- Usable site area and available play fields

#### **CHALLENGES**

- Condition of HVAC and electrical systems
- Accessibility
- Organization of interior spaces
- · Design that accommodates safety and security

#### DESCRIPTION

A stately building, it is placed in grand symmetric fashion on a property flanked by neighborhoods on three sides and grand properties across from the main entrance on Noyes Boulevard. Level grading throughout most of the site has some steep transitions adjoining many properties to the north, south and west. There is a reasonable amount of parking available for staff and visitors, including enough off-street areas for bus and car pickup/dropoff. The building envelope is in very good shape overall, save for some tuckpointing and other items needing repair. The interior, though well-maintained, can't hide the fact that many finishes are simply old and many spaces feel very closed and uninspired. Terrazo floors and stairs, and some original wood floors and cabinetry offer points of interest, but most spaces are of a newer vintage and lack character. Most building systems, particularly electrical, are outdated.

#### BODE HIGH SCHOOL SCORES

building score can range from 1.00 - 4.00

		Bode High School	Buildings of Similar Age	All District Buildings
PHYSICAL CONDITION	Site	1.00	1.81	1.95
			-	
	Fields	2.00	2.47	2.48
	Bleachers	N/A	1.50	1.83
	Envelope	3.00	1.84	2.08
	Roofing	3.33	2.48	2.55
	Interior	1.83	2.51	2.65
	Furniture	3.00	2.92	3.09
	Specialty	2.00	2.62	2.86
ENVIRONMENT	Acoustics	2.50	3.00	3.09
	Daylight & Views	4.00	3.61	3.48
	Safety & Security	3.00	1.93	2.28
	Way finding	1.00	1.39	1.63
	Thermal Comfort	1.00	2.83	3.00
SYSTEMS	HVAC	1.00	2.56	2.82
	Plumbing	3.00	3.17	3.27
	Electrical	2.00	1.93	2.05
	Electrical Power	2.25	2.48	2.61
	Electrical Systems	2.00	1.93	2.08
	Electrical Safety & Security	3.00	2.21	2.31
	Interior Lighting	2.00	2.51	2.64
	Exterior Lighting	1.00	1.17	1.64
GRAND TOTAL		2.20	2.36	2.51

